Oil Field Environmental Incident Summary

Responsible Party: QEP ENERGY COMPANY **Well Operator:** QEP ENERGY COMPANY

Well Name: THOMPSON 1-29/32H

Field Name: GRAIL Well File #: 19323

Date Incident: 3/19/2016 Time Incident: 09:00 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 95 Sec: 29 Qtr: NE NE

Location Description:

Submitted By: Jerry Reinisch Received By:

Contact Person: Jerry Reinisch

1050 17TH ST STE 500 DENVER, CO 80265

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.7 MileDistance Nearest Water Well:0.7 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 1 Barrels 1 Barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Low, Minimal spray from the break in the pipe.

Areal Extent:

Potential Environmental Impacts:

Minimal from the spray that was contained around the wellheads on the drill pad.

Action Taken or Planned:

Well shut in and spray cleaned up from the snow covered surface with a vac truck. More frequent inspections and corrosion evaluations will be conducted on-site.

Wastes Disposal Location: The contents of the vac truck from cleaning out the cellars and the area

that was covered with the spray was transported to Secure Energy via

manifest for disposal.

Agencies Involved:

Updates

Date: 3/21/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC has oversight.